

CLAAS Volto 900 - Reparaturbedürftig ! [342]

Year of manufacture: 2014

Date: 11.01.2025

Design:

Grassland technology + Forage harvesting technology

Category:

Rotary haymaker

€ 4,900.⁰⁰

plus VAT 19% (€ 5,831.⁰⁰ Gross)



Equipment

Working width	8,70
Lighting	✓
Wide distributor	✓
State	Used
Number of rotors	6
Technical condition	defective
Fork loss prevention	✓

Description

- irrtum-zwischenverkauf-vorbehalten-claas-volto-900-baujahr-2014modelljahr-2015
- Working width 8,70m
- 8 rotor bodies with 6 tine arms each
- Cardan shaft
- In need of repair: Bearing on gearbox defective
- zinkenarme-umsetzen-haben-kontakt-